




DKR	C11 – Końcówka prosta ,gwint wew. BSP, stożek 60o			C12 – Końcówka 90o,gwint wew. BSP, stożek 60o			C15 – Końcówka 45ogwint wew. BSP, stożek 60o		
									
DN 06	C11/06/3 G 1/8"	C11/06/1 G 1/4"	C11/06/2 G 3/8"	C12/06/1 G 1/4"	C12/06/2 G 3/8"	C12/06/3 G 1/8"	C15/06/1 G 1/4"	C15/06/2 G 3/8"	C15/06/3 G 1/8"
DN 08	C11/08/2 G 1/4"	C11/08/1 G 3/8"	C11/08/3 G 1/2"	C12/08/2 G 1/4"	C12/08/1 G 3/8"	C12/08/3 G 1/2"	C15/08/1 G 3/8"	C15/08/2 G 1/4"	C15/08/3 G 1/2"
DN 10	C11/10/3 G 1/4"	C11/10/1 G 3/8"	C11/10/2 G 1/2"	C12/10/1 G 3/8"	C12/10/2 G 1/2"	C12/10/3 G 1/4"	C15/10/1 G 3/8"	C15/10/2 G 1/2"	C15/10/3 G 1/4"
DN 13	C11/13/1 G 1/2"	C11/13/2 G 5/8"	C11/13/3 G 3/4"	C12/13/1 G 1/2"	C12/13/2 G 5/8"	C12/13/3 G 3/4"	C15/13/1 G 1/2"	C15/13/2 G 5/8"	C15/13/3 G 3/4"
	C11/13/4 G 3/8"			C12/13/4 G 3/8"			C15/13/4 G 3/8"		
DN 16	C11/16/2 G 5/8"	C11/16/1 G 3/4"		C12/16/2 G 5/8"	C12/16/1 G 3/4"		C15/16/2 G 5/8"	C15/16/1 G 3/4"	
DN 19	C11/19/1 G 3/4"	C11/19/2 G 1"		C12/19/1 G 3/4"	C12/19/2 G 1"		C15/19/1 G 3/4"	C15/19/2 G 1"	
DN 25	C11/25/1 G 1"	C11/25/2 G 1 1/4"		C12/25/1 G 1"	C12/25/2 G 1 1/4"		C15/25/1 G 1"	C15/25/2 G 1 1/4"	
DN 32	C11/32/1 G 1 1/4"			C12/32/1 G 1 1/4"			C15/32/1 G 1 1/4"		